





AFCON/MALHIMIM
ERT room ceiling install











SUT 38.1 LEVEL

OH roll-up door Install ?




HYG SOG platform install Ongoing





West SUT2 Rack 6

04/03/2025 Module 6






HOFFMAN Sparrow E

Rack 4b Inter Connection's


SUT 38.2 LEVEL

Rack 1B Pending lifting EQP




Rack 6 MIMO -Module #1 16.2.25 Rack 2 MIMO -Module #12 10.2.25


SUBFAB BUILDOUT MOD 1




SUBFAB CRC TOPCOAT



BCT Pressure Tests Tomorrow




SUBFAB BUILDOUT MOD 2









































PSSS.1




PSSS.2




PSSS 05/02 Pressure Tests



GUT ROAD CLOSURE 10/02 @ 14:00-18:00














WJG UTILITY LEVEL BUILD OUT


















CUB 1 Exterior Pre-Punch Status




Best Control of the C

- 1. UN2 Lesico piping complete needed to close penetrations
- 2. SWS Make up and Temp shower water lines need to be removed from Building openings
- 3. Boiler room wall repairs Feb 9-19











CUB 2- Load in ,H&T, Framing and Sheetrock















Daily Coordination Meeting

Site LogisticsNorth Entry







Daily Coordination Meeting







Daily Coordination Meeting






Overdue/Open CORs By Subcontractor WW7 (5% Target)

Open – 649 CORs

Overdue – 170 CORs






Overdue/Open CORs By Subcontractor WW7 (5% Target)

Open – 649 CORs

Overdue – 170 CORs





Slips, Trips, Falls

- Seeing an increase in people being injured from slips, trips, and falls. There are some basics that we need to brush up on to help prevent injuries:
 - Use designated walkways, if there is not a designated walkway, alert HCC.
 - Know what your feet are stepping on, do not use phone while walking.
 - Remove boot covers when leaving clean room space
 - Remove tripping hazards, do not just step over/on them.
 - Do not run.
 - Use handrails on stairs.

