

ELRAM BCC room Ongoing












#### SUT 38.1 LEVEL









SUT 38.2 LEVEL


н&т



## SUBFAB BUILDOUT MOD 1




## SUBFAB BUILDOUT MOD 2





















































## PSSS.1



## PSSS.2















## WJG UTILITY LEVEL BUILD OUT













































































**Site Logistics** 







**Site Logistics** 








Site Logistics







**Site Logistics** SW Parking Sanitary





**Site Logistics**<br/>SW Parking







## WATER BOTTLE FILLING & PERSONNEL COOLING STATIONS



### Commissioning

### **WW30**

TCC Predicted: 105 (93 past due)

TCC Completed: 123

Delta: +18 (-75 total)

CCC Predicted: 51 (8 past due)

CCC Completed: 37

Delta: -14 (-22 total)

GT Predicted: 119 (24 past due)

GT Completed: 41

Delta: -78 (-102 total)




## Both Feet on the Floor of MEWPs

- As access to our WAH activities becomes more complex, we are seeing an increase in employees elevating themselves above guardrails to access their work.
- Whether we are working near an MEWP guardrail, a scaffold guardrail, or leading edge guardrails- we cannot elevate ourselves above that guardrail without additional fall protection measures.
- It is NEVER permitted to stand on the toe board, mid-rail, or top rail of any guardrail system as it is not an appropriate standing surface for work to take place.
- If a person has appropriate additional fall protection means, an approved plan, and an appropriate work surface- we can assess if elevating ourselves above the guardrail can be done safely.





# Heat Index- July 29th



## **Extreme Caution**

- Ensuring water and shaded areas available
- **Acclimating workers**
- Emergency planning and response
- Training workers and supervisors on the signs of heat stress and preventative measures
- Modified work schedules and/or rotating out workers
- Monitoring of workers for signs of heat stress

